ISLEVER

920-127

NNCSS Succession BCM 3.0 Exam

DEMO

https://www.islever.com/920-127.html

https://www.islever.com/nortel.html

QUESTION NO: 1

You are configuring the remote site of a multi-site BCM 3.0 network for DHCP. The clients at the remote sites are trying to use the main site as a centralized DHCP server. The local clients are getting IP Addresses, but the remote clients are not. What must be configured to allow the remote clients to obtain IP addresses?

A. DHCP Server
B. Excluded Addresses
C. DHCP Relay Agent
D. Reserved Addresses

Answer: C

QUESTION NO: 2

A customer wants you to add a BCM 3.0 to their network and suspects the default settings may cause problems. You decide to connect to the serial port of the BCM 3.0 and use a terminal emulator to check the IP settings. What type of direct connect cable would you use to access the BCM 3.0?

A. cross-over DB9 female to DB9 male
B. RS232
C. null modem DB9 female to DB9 female
D. RJ45 patch cable

Answer: C

QUESTION NO: 3

You have just installed a new set for extension 2223. Extension 2223 has target line number 260 which is programmed to appear and ring on the set. You have allowed call log space for this extension, and activated "log all calls". If the user at extension 2223 misses a call, the set does not display "calls for you". What has NOT been programmed?

A. Increase the Call Log space assigned to extension 2223
B. Reinstall voicemail and increase the Call Log space
C. Reset all Call Log space
D. Call Log Set "Y"

Answer: D

QUESTION NO: 4

You are installing a BCM 3.0 with a FEM, DSM-16 and DTM. You are having difficulty getting the DSM-16 and DTM to function. Looking at the FEM module you notice all LED's are green next to the fiber ports. What should you do to correct this condition?

A. Turn off 3 dip switches on the FEM and make sure the DSM-16 and DTM are using those DS-30 resources.
B. Turn off 2 dip switches on the FEM and make sure the DSM-16 and DTM are using those DS-30 resources.
C. Turn off 1 dip switch on the FEM and make sure the DSM-16 and DTM are using those DS-30 resources.
D. Reboot the BCM 3.0

Answer: B

QUESTION NO: 5

You are configuring NAT on a BCM 3.0 in order to publish an FTP site that is on the private network. The FTP server has an IP address of 192.168.254.21 with a subnet mask of 255.255.255.0. When you build the inbound NAT rule, what do you use for a private subnet mask?

A. 255.0.0.0
B. 255.255.255.0
C. 255.255.0.0
D. 255.255.255.255

Answer: D

QUESTION NO: 6

Your customer is currently running in an unreliable network due to service provider outages. They are requesting that IP Trunk calls be routed automatically over the PSTN during these outages. What service would need to be activated and configured to detect these outages in order to allow the calls to be re-routed?

A. Console Service
B. Alarm Service
C. QoS Monitor
D. Policy Management

Answer: C

QUESTION NO: 7

A BCM 3.0 with an optional expansion cabinet needs a DS256 adapter cable to be installed. How do you ensure the physical connection is secure?

A. Ensure the cable is connected to the media services card.
B. Make sure there is a line connected to the modem card.
C. Ping the LAN card from the customer's network.
D. Check the fiber connection on the FEM.

Answer: A

QUESTION NO: 8

A customer wants to ensure that the default IP settings on a BCM 3.0 will not conflict with the customer's network. What is the default IP address of LAN 1 on the BCM 3.0?

A. 10.10.11.1
B. 10.1.1.1
C. 10.10.10.1
D. 192.168.254.1

Answer: C

QUESTION NO: 9

You are configuring a BCM 3.0 for MCDN over IP with a Meridian 1 ITG. The big feature the customer is interested in is tromboning on both forwarded and transferred IP trunk calls. What features must you ensure are enabled in the BCM 3.0 and Meridian 1?

A. TAT and ICCL
B. TAT and NAT
C. TAT only
D. TAT and TRO

Answer: D

QUESTION NO: 10