I S L E V E R

920-432

Communication Server 1000 Rls.5.0-BCM

Rls.4.0 Multi-site

DEMO

QUESTION NO: 1

What may be a cause of echo on a VoIP network?

A. the VoIP products on the network
B. the CODEC used on the VoIP network
C. poor-quality headphones used on the VoIP network
D. MCDN network features configured on the VoIP network

Answer: C

QUESTION NO: 2

All systems on centralized voicemail must use what kind of dialing plan?

A. CDP
B. FNP
C. ESN
D. UDP

Answer: A

QUESTION NO: 3

Based on the exhibit showing the H.323 settings.

H323 GW Settings

Primary gatekeeper IP address	47.104.36.76
Alternate gatekeeper IP address	0.0.0.0
Primary Network Connect Server IP address	47.104.36.76
Primary Network Connect Server Port number	16500	Range: 1024 to 65535
Alternate Network Connect Server IP address	0.0.0.0
Alternate Network Connect Server Port number	16500	Range: 1024 to 65535
Primary Network Connect Server timeout	10	Range: 1 to 30

Telephony Resources

Modules

Bus	Prog Type	Actual Type	Dip Sw	State	Devices	Low	High	Total	Busy
0	N/A	IP Trunks	N/A	N/A	Lines	1	60	N/A	N/A
1	N/A	IP & App Sets	N/A	Enabled	Sets	N/A	N/A	8	0

Disable   Enable

Details for Module: 0

Routing Table | IP Trunk Settings | H323 Settings | H323 Media Parameters | SIP Settings | SIP Media Parameters | SIP URI Map

Telephony Settings

Fallback to circuit-switched	Disabled	Gatekeeper digits	
Gateway protocol	CSE	Gatekeeper wildcard	☐

Configuration

Call signaling	Gatekeeper Resolved	Call signaling port	1720
Enable H245 tunneling	☐	RAS port	0
Primary Gatekeeper IP	47.104.36.80	Registration TTL (s)	60
Backup Gatekeeper(s)	0.0.0.0	Gatekeeper TTL (s)	0
Alias names	Name:BCM-1	Modify...	

Status   Attempting to discover gatekeeper at 47.104.36.80

ActualTests

What is causing problems with the Communication Server (CS) 1000 - Business Communications Manager (BCM) integration?

A. An alternate gatekeeper has not been defined.
B. The RAS port has not been defined on the BCM.
C. The Primary Gatekeeper IP address does not match.
D. The Primary Network Connect Server Port number does not match the Call signaling port.

Answer: C

QUESTION NO: 4

When should you change the RTP over UDP port range configuration on a Business Communications Manager (BCM)?

A. when you are configuring a CS 1000 and BCM VoIP network integration
B. when only absolutely necessary in instances where port configurations are causing conflicts
C. when you have multiple BCM systems in a CS 1000 and BCM VoIP network integration
D. when you are configuring a multisite BCM VoIP network integration

Answer: B

QUESTION NO: 5

The Message Wait Indication is not working on a Business Communications Manager remote site.

Based on the exhibit showing Centralized Voice Messaging, what is the issue?

A. The Link to the external directory is not active.
B. The External Number does not contain the proper access code.
C. The Message Waiting Cancellation String has not been configured.
D. The Message Wait Indication String must use the mailbox number assigned by CallPilot.

Answer: D

QUESTION NO: 6

The remote Business Communications Manager is having difficulty getting its voicemail to work.