ISLEVER

200-401

Managing Industrial Networks with Cisco Networking Technologies

DEMO

https://www.islever.com/200-401.html https://www.islever.com/cisco.html

For the most up-to-date exam questions and materials, we recommend visiting our website, where you can access the latest content and resources.

QUESTION 1

Which of the following correctly pairs the dotted decimal subnet mask with the correct number of binary

bits that represent the subnet mask?

- A. 255.255.255.192 and /25
- B. 255.255.255.248 and /28
- C. 255.255.255.224 and /26
- D. 255.255.255.248 and /27
- E. 255.255.255.240 and /28
- F. 255.255.255.240 and /16

Answer: E

QUESTION 2

in terfa ce FastEthe m et 1/1	1
switchport access vlan 102	interface Vlan101
E.	ip address 192.168,1.1 255.255.255.0
in terface FastEthe m et1/2	cip e nable
switchport access vlan 104	1
1	interface Vlan102
in terfa ce FastEthe m et 1/3	ip address 192.168.2.1 255.255.255.0
switchport access vian 103	cip e nable
1	1
interface FastEthemet1/4	interface Vlan103
switchport access vian 101	ip address 192.168.3.1 255.255.255.128
E.	cip e nable
interface FastEthemet1/5	1
switchport trunk native vlan 103	interface Vlan104
switchport mode trunk	ip address 192.168.3.129 255.255.255.128
L.	cip e nable
in terfa ce Vlan 1	!
no ip address	ip classless

Refer to the exhibit. Which port should a PLC with IP address 192.168.3.65 be plugged into in order to communicate to the rest of the network?

- A. FastEthernet1/1
- B. FastEthernet1/2
- C. FastEthernet1/3
- D. FastEthernet1/4
- E. FastEthernet1/5

Answer: C

QUESTION 3


Which option allows an EtherNet/IP I/O device to be safely installed where it is subject to water

immersion?

- A. The device is rated IP20 and the power wiring is installed securely to the terminal block.
- B. The device is rated IP67 and a power cordset is used.
- C. The device is rated IP67 and immersed to 10 m.
- D. The device is rated IP20 and immersed to 10 m.

Answer: B

QUESTION 4



What are three traffic and interconnection requirements for the devices in the exhibit? (Choose three.)

A. The EtherNet/IP drive connections are in a high-voltage area and need protection from electromagnetic noise, so shielded cable that is rated for 600 V is advised.

B. EtherNet/IP devices such as the controller, drive, VoIP phone, and IP camera should be in the same VLAN.

C. CIP traffic has the highest bandwidth requirement so it needs the highest QoS setting.

D. EtherNet/IP drive traffic has high sensitivity to random drops, latency, and jitter.

E. Real-time motion control and VoIP traffic can share the same VLAN with the proper QoS setting.

F. IEEE1588 and PTP are important for ensuring real-time synchronization.

Answer: ADF

QUESTION 5